

	Type	L #	Hits	Search Text
1	BRS	L1	828	linear same reluctance same motor
2	BRS	L2	226	linear same reluctance same motor same control
3	BRS	L3	53	linear same reluctance same motor same control same (switch or switched)
4	BRS	L4	0	linear same reluctance same motor same control same (switch or switched) same "D.C. current"
5	BRS	L5	4	linear same reluctance same motor same control same (switch or switched) same DC
6	BRS	L6	0	"53434811".pn.
7	BRS	L7	2	"5343811".pn.
8	BRS	L8	2	"5479145".pn.
9	BRS	L9	2	"6044770".pn.

	DBs	Time Stamp	Comments	Error Definition	Errors
1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 16:15			
2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:07			
3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:08			
4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:09			
5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:13			
6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:13			
7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:17			
8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:19			
9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:19			

	Type	L #	Hits	Search Text
10	BRS	L10	21	("2412512"   "2666879"   "3233559"   "3470828"   "3662689"   "3771033"   "3806782"   "3834317"   "3904941"   "3913493"   "4299173"   "4641065"   "4646651"   "4779538"   "4913059"   "5085149"   "5628252").PN.
11	BRS	L11	17	linear same reluctance same motor same (multi or poly) same phase
12	BRS	L12	2	"5722326".pn.
13	BRS	L13	15	"2257773"

	DBs	Time Stamp	Comments	Error Definition	Errors
10	US-PGPUB; USPAT; USOCR	2005/07/14 15:21			
11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:49			
12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:51			
13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 15:51			

	Type	L #	Hits	Search Text
14	BRS	L14	45	( "3506862"   "3540541"   "3691368"   "3736880"   "3768417"   "3774025"   "3803466"   "3827371"   "3828236"   "3847089"   "3848836"   "3874301"   "3880088"   "3904942"   "3934183"   "3937431"   "3967801"   "3974778"   "3979092"   "4014503"   "4061089"   "4068152"   "4142700"   "4166599"   "4305485"   "4348618"   "4381478"   "4471356"   "4651071"   "4652800"   "4665349"   "4690066"   "4700119"   "4709639"   "4716346"   "4718621"   "4721045"   "4721892"   "4800818"   "4819564"   "4836344"   "4853602"   "4931677" ) .PN.
15	BRS	L15	1	"5936373".pn.
16	BRS	L16	3	( "5289107"   "5315224"   "5545938" ) .PN.
17	BRS	L17	30	( "5545938" ) .URPN.
18	BRS	L19	0	linear same reluctance same motor same "multi-phase" same DC

	DBs	Time Stamp	Comments	Error Definition	Errors
14	US-PGPUB; USPAT; USOCR	2005/07/14 15:54			
15	US-PGPUB; USPAT; USOCR	2005/07/14 15:54			
16	US-PGPUB; USPAT; USOCR	2005/07/14 16:05			
17	USPAT	2005/07/14 16:10			
18	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 16:15			

	Type	L #	Hits	Search Text
19	BRS	L18	10	linear same reluctance same motor same "multi-phase"
20	BRS	L20	14	linear same reluctance same motor same multi same phase
21	BRS	L21	4	linear same reluctance same motor same multi same phase same excitation

	DBs	Time Stamp	Co mm en ts	Er ro r De fi ni ti on	Err ors
19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 16:17			
20	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 16:17			
21	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/14 16:18			